ENGINEERING CHANGE NOTICE

DART AEROSPACE LTD	Amendment Design Review (ADR) Yes/No: Y	<u></u>
Date: 06.09.22	ADR Date: 06.09.15	,0
Job No: 00064	Created By: Checked By: PH	
Product No: D412-702	Approved By: Approved By:	
Product Name: SHOULDER HARNESS KITS	Approved By: (Proj. Manager) (Management if reqd)	
Documents Affected:	OD. V	

RELEASE DSI 9351-A, D3551-A AND D3546-A.

#	Engineering Actions	Yes	No	Responsible	To happen by:	Complete	
1	Required Documents/Drawings Under Review?		Х				
2	Update Blue/Pink Folder/Electronic File	Х		KJ/LE	16.09.26	06.09.26 Kg LE	
	Update DSI Folder/Electronic File	Х		KJ/LE		06.09.26 HJ LE	
	Update D-Part Master Binder	Х		KJ		06.09.2640	
5	Update Grey Project Binder	Χ_		KJ/LE_		06.09.25 GE	
	Update DEO/DSI Binder	Х		KJ		06.09.2619	
7	Update Master Document List (MDL)	×		KJ_		06.09.26	
8	Update Document Record (DR)	. X		KJ		06.09.26 ts.	
9	Update Change Record Form	X		Y		Ob. 09. 26 424	
10	Move Electronic File	Х		KJ		06 09 26 10	
11	Notify TC of Change		Х			0	
12	Notify FAA of Change		Х				
	Update QSI 021 (TC/FAA STC)		Х				
14	Update QSI 036 (K-Kits)		Х				
15	Update Accpac Database	X		KJ		Ob 09.26 \$.	
16	Update Access Database	Х		KJ		06.09:26	
17	Verification ARC		Х			0	
18	Update STC Approval List		X				
19	Update Product Development Summary		Х			11	
20	Create/Update COSS (Estimate/BOM)	Х		JLM/EC		ps/06.09.27	
21	Create/Update PPP's	X.		KJ		9.09.26 9st :	
22	Update Paperwork Kits in Production	Х		KJ		NONE IN Prod \$	
23	Update Paperwork Kits in Stock	Х		LL		06.10.25 9	
24	Red Tag Stock with old CHG #		Х				
25	Rework/Scrap Current Production	Х		LL		606-10.25 PY	
26	Rework/Scrap Kits in Stock?	Х		LL		I for w	
	Update Qpulse/Laminated Dwgs		Х				
28	Create/Update Controlled PDF Files	Х		KJ		06.09.26 1	
	Create/Update FAI sheets	Х		JLM_		(M/0009-27)	
30	Create/Update CNC Programs	Х		JLM/EC		Just 1009.27	
	Create/Update Tooling		Х				
	MPP required?		Х		1		
33	Notify Previous Customers	Х		BB/PM/JL	Y	NM 21.12.06	
	Notify Eurocopter France		Х			<u> </u>	
35 36							
36							

Description / Action:

Proceed as indicated above.
-DSI 9351-011/013/015/017 @ CHG 00 1
-NO CHANGE TO CHG # FOR 9-DIGIT PER SERGE SHAHBAZIAN
-INCLUDE DSI 9351 TO EXISTIN C FUTURE KITS -INCLUDE DST PARTS.

ECN Complete:

Date: 04



To:	Summit Helicopter Inc. Attn: Richard Day	From:	Holly Menard Sales Associate Dart Helicopter Services
Fax:	1 540 992 5503	Fax:	613-632-4443
Phone:	1 540 992 5500	Phone:	613-632-3336
# of page	es 2 (including cover)	Email:	hmenard@dartaero.com
Date:	11/20/2006		
Subject:	DSI 9351 Shoulder Harness Ir	nprovement Kit	

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Ġ

Holly Menard
Sales Associate
DART Helicopter Services, LLC
hmenard@dartaero.com
www.darthelicopterservices.com
"we're more than just skidtubes"





To:	River City Helicopters	From:	Holly Menard		
	Attn: Maintenance Dept.		Sales Associate		
	-		Dart Helicopter Services		
Fax:	1 208 773 1036	Fax:	613-632-4443		
Phone:	1 208 773-1111	Phone:	613-632-3336		
# of page	es 2 (including cover)	Email:	hmenard@dartaero.com		
Date:	11/20/2006				
Subject: DSI 9351 Shoulder Harness Improvement Kit					

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC
hmenard@dartaero.com
www.darthelicopterservices.com
"we're more than just skidtubes"

में द्रापाड

DS1 9351-013 X1

gack Scanlan

04376

Holly Menard

From:

Holly Menard [hmenard@dartaero.com]

Sent:

Monday, November 20, 2006 10:21 AM

To:

'Devlin Talkington'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Devlin,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166 Cell: 1.613.676.1720 Fax: 1.613.632.4443

hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

04375

Holly Menard

From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:21 AM

To: 'cbrown@sjhelicopters.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Chris.

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166

Cell: 1.613.676.1720 Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.







Helicopter Maintenance Corp.	From:	Holly Menard		
Attn: Maintenance Dept.		Sales Associate		
-		Dart Helicopter Services		
1 208 345 6719	Fax:	613-632-4443		
1 208 344 6521	Phone:	613-632-3336		
es 2 (including cover)	Email:	hmenard@dartaero.com		
11/20/2006				
DSI 9351 Shoulder Harness Impr	ovement Kit	t		
	Attn: Maintenance Dept. 1 208 345 6719 1 208 344 6521 es 2 (including cover) 11/20/2006	Attn: Maintenance Dept. 1 208 345 6719		

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC
hmenard@dartaero.com
www.darthelicopterservices.com
"we're more than just skidtubes"

From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:13 AM

To: 'richie@helicopter.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Richie.

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166 Cell: 1.613.676.1720

Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:13 AM

To: 'David Covert'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear David,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166

Cell: 1.613.676.1720 Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.





From:

Holly Menard [hmenard@dartaero.com]

Sent:

Monday, November 20, 2006 10:12 AM

To:

'jb@aerowesthelicopters.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear JB,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166

Cell: 1.613.676.1720 Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.



From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:16 AM

To: 'helimax@goldstate.net'

Subject: DSI 9351 Shoulder Harness Improvement Kit

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166

Cell: 1.613.676.1720
Fax: 1.613.632.4443
hmenard@dartaero.com

www.darthelicopterservices.com
"we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

From:

Holly Menard [hmenard@dartaero.com]

Sent:

Monday, November 20, 2006 10:18 AM

To:

'suruhqw@heliqwest.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Suru.

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166

Cell: 1.613.676.1720 Fax: 1.613.632.4443

hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

Holly Menard [hmenard@dartaero.com] From:

Monday, November 20, 2006 10:14 AM Sent:

To: 'jnorling@hillsboro-aviation.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear John,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166 Cell: 1.613.676.1720 Fax: 1.613.632.4443

hmenard@dartaero.com

www.darthelicopterservices.com "we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

From:

Holly Menard [hmenard@dartaero.com]

Sent:

Monday, November 20, 2006 10:18 AM

To:

'greg_k@helitrade.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Greg,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard

Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166

Cell: 1.613.676.1720

Fax: 1.613.632.4443
hmenard@dartaero.com

www.darthelicopterservices.com

"we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:19 AM

To: 'dave@pjhelicopters.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Dave.

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166 Cell: 1.613.676.1720 Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com
"we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.



From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:22 AM

To: 'LEE SMITH'

Subject: DSI 9351 Shoulder Harness Improvement Kit

Dear Lee,

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate
DART Helicopter Services, LLC

Tel: 1.613.632.3336

1.800.556.4166 Cell: 1.613.676.1720

Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com
"we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

From: Holly Menard [hmenard@dartaero.com]

Sent: Monday, November 20, 2006 10:20 AM

To: 'info@rogershelicopters.com'

Subject: DSI 9351 Shoulder Harness Improvement Kit

We would like to inform you that Dart Aerospace Ltd if offering a product improvement kit to customers who have recently installed a 5 Man Fwd Facing Shoulder Harness Kit P/N D412-702-023 in their aircraft.

Please see the attached Service Instructions for details. If you would like to receive the DSI 9351-013, please contact me and I will be pleased to provide you with this kit.

Do not hesitate to contact me if you have any questions or concerns regarding this product improvement kit.

Warm regards,

Holly Menard
Sales Associate

DART Helicopter Services, LLC

Tel: 1.613.632.3336 1.800.556.4166

Cell: 1.613.676.1720 Fax: 1.613.632.4443 hmenard@dartaero.com

www.darthelicopterservices.com
"we're more than just skidtubes"

No virus found in this outgoing message.

Checked by AVG Free Edition.

Version: 7.5.430 / Virus Database: 268.14.10/541 - Release Date: 11/20/2006 6:48 AM

No virus found in this incoming message.

Checked by AVG Free Edition.

ENGINEERING CHANGE NOTICE

	1 1 2	
DART AEROSPACE LTD	Amendment Design Review (ADR) Yes/No: Y ADR Date: 06.09.15	
Date: 06.09.22 Job No: 00064	Created By: Checked By: Pt	
Product No: D412-702 Product Name: SHOULDER HARNESS KITS	Approved By: (Proj. Manager) (Management if reqd)	
Documents Affected:		

RELEASE DSI 9351-A, D3551-A AND D3546-A.

1		Ves	No	Responsible	To happ	en by:	Complete
#	Engineering Actions	Yes	X	Responsis			
1	Required Documents/Drawings Under Review?		├ ~-	KJ/LE	Up. 00	1.26	06.09.26 Kg 18
2	Update Blue/Pink Folder/Electronic File	X		KJ/LE	47.0		ab. 09.26 + 13
3	Update DSI Folder/Electronic File	X	 	KJ			06.09.26
4	Update D-Part Master Binder	×		KJ/LE			00.09 25 CE
5	Update Grey Project Binder	X	├ ──┤	KJ			06.09.2613
6	Update DEO/DSI Binder	Х		KI			06.09.26
7	Update Master Document List (MDL)	X		KJ			06.09.26
8	Update Document Record (DR)	Х			 		Cb. 09 26 454
9	Update Change Record Form	X	122	KJ			06 09 26 18
10	Move Electronic File	×		KJ			0
11	Notify TC of Change		×				
12	Notify FAA of Change		×		 		
13	Update QSI 021 (TC/FAA STC)		×				2 · .
14	Update QSI 036 (K-Kits)		Х		 	`	d. 19.26 xx.
15	Update Accpac Database	×		KJ			06.09.26 Kg
116	Update Access Database	Х		KJ			00101.00
	Verification ARC		Х		 		
18	Update STC Approval List	I	×		ļ -		21
10	Update Product Development Summary		X				1 de 100 050 27
20	Create/Update COSS (Estimate/BOM)	Х		JLM/EC	 		00000
21	Create/Update PPP's	Х		KJ	 		Marie in Prod St
22	Update Paperwork Kits in Production	Х		KJ	 		100 10 25 OK
22	Update Paperwork Kits in Stock	Х		LL	 	<u></u>	(D. W. 29 1 3
2/	Red Tag Stock with old CHG#	T	X		 ,, +	01.620	7.06.10.25
25	Rework/Scrap Current Production	Х		LL	 	1.0.1 10	Con W
26	Rework/Scrap Kits in Stock?	X	I	LL	 \/ -	<u> </u>	701
27	Update Qpulse/Laminated Dwgs		×		 		No. 09. 21. H.
28	Create/Update Controlled PDF Files	Х		KJ	 		10.00
20	Create/Update FAI sheets	Х		JLM	 		1100072
30	Create/Update CNC Programs	Х		JLM/EC	1		Judit March Coll
	Create/Update Tooling		×		 		
	MPP required?	T	×		 	<i>7</i>	11 M 21.12 - 64
32	Notify Previous Customers	×		BB/PM/JL	 		HUICALIA CO
	Notify Eurocopter France	T	×		1		
35							
36		1					<u> </u>
30	1	-					•

Description / Action:

Proceed as indicated above.
-DSI 9351-011/013/015/017 @ CHG 00 1
-NO CHANGE TO CHG # FOR 9-DIGIT PER SERGE SHAHBAZIAN

-INCLUDE DS19351 TO EXISTIN & FUTURE KITS -INCLUDE DST PARTS

Date: 07



DESIG	N ———	DRAWN BY	DART AEROSPACE L HAWKESBURY, ONTARIO, CANA	
CHEC	ŒD	APPROVED	DRAWING NO.	REV. A
1 .	D .	-#	DSI 9351	SHEET 1 OF 1
DATE	.1	L	TITLE	SCALE
	06.0	9.15	SHOULDER HARNESS KIT	NTS
REV		DATE	DESCRIPTION	
A		06.09.15	NEW ISSUE	

그는 이 교육 사람들이 나는 그는 이번 사람들이 살아왔다. 아니라 살아왔다는 아이는 사람이 되었다.

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D412-702 REV A, B OR C

REF. CANADIAN STC SH04-7 REF. FAA STC SR01997NY


TO IMPROVE THE FIT AND VISUAL IDENTIFICATION OF SHOULDER HARNESS SETS, DSI 9351-011/-013/-015 SHOULDER HARNESS UPGRADE KITS ARE AVAILABLE FOR THE D412-702-011/-021/-013/-023/-015/-025/-017/-027 AND D214-702-035 SHOULDER HARNESS KITS AT CHANGE 1. INSTALLATION OF THESE KITS IS OPTIONAL.

FOR DSI 9351-011/-013 KITS, FOLLOW STEPS 1 AND 2. FOR DSI 9351-015/-017 KITS, FOLLOW STEP 2:

1) REMOVE THE MS24694-S152 SCREWS FROM THE D3196-1 BAR ON THE CENTRAL PANEL. RE-INSTALL THE D3196-1 BAR WITH D3546-1 CLIPS USING MS24694-S154 SCREWS AS SHOWN IN FIGURE 1. ENSURE THAT THE SHOULDER BELTS ARE LOOPED THROUGH THE CLIP AS SHOWN IN DETAIL 'A'. TORQUE SCREWS TO 100-140 in-lbs (11.3-15.8 N-m). IT IS ACCEPTABLE TO USE LONGER MS24694-SXXX SCREWS AS REQUIRED TO ENSURE THAT THE D3196-1 BAR IS PROPERLY SECURED.

2) INSTALL THE D3551-11 HOOK AND LOOP TIES THROUGH THE FRONT LOOPS OF EACH SET OF SHOULDER BELTS. INSTALLATION ON THE 4-MAN AFT FACING BENCH IS AT THE DISCRETION OF THE INSTALLER. ENSURE THAT THE 'LOOP' SIDES OF THE TIES ARE FACING OUTWARD FOR PASSENGER COMFORT. TIGHTEN OR LOOSEN THE TIES AS NEEDED (TRIMMING IS ACCEPTABLE).

OTY -011	QTY -013	OTY -015	QTY -017	P/N	DESCRIPTION	INSTALLS ON:
Y	Q.1. V.1.			DSI 9351-011	13-MAN UPGRADE KIT	D412-702-011/-021
	Y			DSI 9351-013	5-MAN UPGRADE KIT	D412-702-013/-023
	- 	X		DSI 9351-015	5-MAN UPGRADE KIT	D214-702-035
			х	DSI 9351-017	4-MAN UPGRADE KIT	D412-702-015/-017/-025/-027
		5	4	D3551-11	HOOK AND LOOP TIE	X
13	5	- 3	<u> </u>	D3546-1	CLIP	X
1 2	1 - 5	 	<u> </u>	MS24694-S154	SCREW	<u> </u>



COPYRIGHT © 2006 BY DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Inventory Worksheet (ICWK04)

cation: MAIN Main Finished Goods Location

Worksheet Creation Date: 13/03/2007 Worksheet Comment:

Item Number / [Description	Picking Sequence		Unit of Measure	Lot Quantity on Hand Lot Number Quantity Counted
D412702021	13 Man Shoulder Harness	FG 41	3.000	DEACH	1.00 25853 (2.00 29925) 3.00
D412702023	5 Man Shoulder Harness	FG 33	7.000	0 EACH	2.00 25765 1.00 26074 4.00 30123 7.00
D412702025	4 Man Shoulder Harness	FG 33	8.000	0 EACH	1.00 25444 1.00 257661 2.00 27249 4.00 30124
∪ items printed		7			

Thursday, 28/09/2006 2:25:22 PM Linda Lacelle **Process Sheet** : CC-DAR01 Dart Aerospace Ltd. / winer Drawing Name : D412-702 A Number : 28754 .stimate Number : 10804 ECN850 Attached P.O. Number : NIA : Z CUSTOM Part Number This Issue : 28/09/2006 5.0. No. : NAT **Drawing Number** : UPDATE PER DSI 9351A Prsht Rev. : NC : IM/A Project Number : KIA First Issue Type : OVERHEAD Drawing Revision : NIM Previous Run : 00015 Material : NIA Written By Due Date : 05/10/2006 Qty: Checked & Approved By 20 Um: Each Comment Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 REMOVE KITS FROM STOCK: 1 D412-702-011 B PA 5 1 Rus PA D412-702-013 B D412-702-015 B D412-702-017 B 4 D412-702-021 B B26563 3x B25553 5 D412-702-023 B 21765 24 B26614 3K - D412-702-025 B 26075 DX B25444 IX B25766 IX B27349 2X D412-702-027 B & D412-702-031-B-035 B 26101 V (1) 2.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 ADD TO KITS IN STOCK **NEW PAPERWORK** DSI 9351-A 1/4/11/27

Dogo 4

Date:

Tuesday, 13/03/2007 12:00:34 PM

User:

Linda Lacelle

"Where Used" Report

Item Number: DSI9351011

In Job History

Job No.	Part Number	Seq.	Parts	S.O. No.	Date	Due Date	Cost	Employee
Item: DSI93510	11							
28754 Z_CUSTOM	CUSTOM	4.0	4.000		21/11/2006	1.1	\$385.66	LACE01
		·	4.000				\$385.66	
Total Records Retri	eved :	1	4.000				\$385.66	

Date:

Tuesday, 13/03/2007 12:02:17 PM

User:

Linda Lacelle

"Where Used" Report

Item Number: DSI9351013

In Job History

Job	No. Part N	umber Seq.	Parts	S.O. No.	Date	Due Date	Cost	Employee
ltem:	DSI9351013							
28754	z_custom	5.0	4.000		21/11/2006	1.1	\$291.36	LACE01
			4.000				\$291.36	
Total Re	cords Retrieved :	1	4.000				\$291.36	

Date:

Tuesday, 13/03/2007 12:02:54 PM

User:

Linda Lacelle

"Where Used" Report

Item Number: DSI9351015

In Job History

Job No.	Part Number	Seq.	Parts	S.O. No.	Date	Due Date	Cost	Employee
Item: DSI935	51015			·				
28754	Z_CUSTOM	6.0	1.000		21/11/2006	1.1	\$28.13	LACE01
	<u> </u>		1.000		,		\$28.13	
Total Records Retrieved :		1	1.000				\$28.13	